





SYMBOL	USE	T	S	R	SOURCE
U1	MOTOL				
V1					
W1					
R41	RUNNING				
R51					
J11	ABNORMAL				
JC1					
V11	DRAIN V/V				
T11	AIR TEMP. HIGH				
T21					
T31					
T41					
P11	OIL PRESS LOW				
P21					
T31	WATER TEMP. HIGH				
T41					
P71	PRESS SWITCH				
P81					
H11	HEATER				
H21					
D31	E.C.C				
D41					
Q1	RUNNING				
Q2					
Q3					
Q4					
Q5					
Q6					
Q7					
Q8					
Q9					
Q10					
Q11					
Q12					
Q13					
Q14					
Q15					
Q16					
Q17					
Q18					
Q19					
Q20					
Q21					
Q22					
Q23					
Q24					
Q25					
Q26					
Q27					
Q28					
Q29					
Q30					
Q31					
Q32					
Q33					
Q34					
Q35					
Q36					
Q37					
Q38					
Q39					
Q40					
Q41					
Q42					
Q43					
Q44					
Q45					
Q46					
Q47					
Q48					
Q49					
Q50					
Q51					
Q52					
Q53					
Q54					
Q55					
Q56					
Q57					
Q58					
Q59					
Q60					
Q61					
Q62					
Q63					
Q64					
Q65					
Q66					
Q67					
Q68					
Q69					
Q70					
Q71					
Q72					
Q73					
Q74					
Q75					
Q76					
Q77					
Q78					
Q79					
Q80					
Q81					
Q82					
Q83					
Q84					
Q85					
Q86					
Q87					
Q88					
Q89					
Q90					
Q91					
Q92					
Q93					
Q94					
Q95					
Q96					
Q97					
Q98					
Q99					
Q100					

DRAW No. SHC-1002	
file name 1002MCD01	SHEET No. 11
TITLE	
CIRCUIT DIAGRAM	
SCZX	
R L V	



DRAW No. SHC-1002

file name 1002MCD01 2 SHEET No. 12

TITLE CIRCUIT DIAGRAM

SCZX

R L V