



REQUEST FOR QUOTATION

Vendor Name	WRIST SHIP SUPPLY SPAIN S.L.	PR Type	Spare	Priority	Within 1 month
PR Number	SPR/CNTN/D/26/042	Vessel	CNTN - GENCO CONSTANTINE	Supply Date	04/30/2026
Ship Builder	Imabari Shipbuilding Ltd, Imabari, Japan	Hull No	S - 8071	Supply Port	GIBRALTAR - GIBRALTAR
PR Description	CISCO - IP PHONE RECEIVER SPARE FOR CAPTAIN CAPIN.				

MACHINERY DETAILS					
Machine Name	IP PHONE	Model	CP - 7821	Address	
Maker	CISCO	Year Of Mfg.		http://cisco-returns.com.	
		Serial No			

SNo	Item Description	Component No./ Part No.	Drawing No.	Item No	Req Qty.	Uom	Remarks
1	CISCO IP PHONE RECEIVER	CP - 7821	SEE ATT. PIC.	3844 - 13 - 1086	2	PIECES	Kindly note that the Cisco IP phones installed in the Captains cabin and on the bridge are having issues with their receivers. The receiver sound level is very low. already spare receiver used from spare IP phone and no spare onboard.