



REQUEST FOR QUOTATION

Vendor Name	MARINE MECHANICS INC FZE	PR Type	Repair	Priority	Within 1 month
PR Number	SPR/PCRD/D/25/037	Vessel	PCRD - GENCO PICARDY	Supply Date	02/13/2025
Ship Builder	Nantong COSCO KHI Ship Engineering.Co	Hull No	NE027	Supply Port	JIANGYIN - CHINA
PR Description	SCBA and Med oxygen Annual inspection and filling				

MACHINERY DETAILS

Machine Name	LSA-Related Components-LSAC	Model	None	Address	
Maker	None	Year Of Mfg.			
		Serial No			

SNo	Item Description	Drawing No.	Req Qty.	UOM	Remarks
1	Med oxygen Annual inspection and filling		5	NUMBER	Required annual inspection of Med Oxygen Cylinders: 40 ltrs 1 number + 3 ltrs 4 numbers
2	SCBA Annual inspection and filling		9	PIECES	Required annual Inspection of SCBA sets along with SCBA cylinders.
3	Quality test of foam component		2	SETS	Quality test of foam component for the foam applicators in engine room along with annual inspection of complete foam applicator sets